



# Harris Plant

MFP Outboard Seal  
Excessive Leakage




Main Feed Pump Diagram  
Ingersoll-Rand (Flowserve) 16X19-2CA



ITEM	DESCRIPTION
8	Shaft Sleeve
88A	Stuffing Box Bushing
264 A/B	Stuffing Box Extension
323A/B	Compression Ring
363P	Seal Gasket

**Stuffing Box with Serrated Bushing Diagram**



STEAM GENERATOR FEED PUMP SEAL WATER SYSTEM



B813E  
2A

B809B

008

12.19.2016 10:41